

## NOTES:

1. INTERPRET DRAWING PER: ASME Y14.5-2009 DIMENSION AND TOLERANCING.

- 2. REMOVE ALL BURRS AND SHARP EDGES.
- 3. ALL SURFACES ARE TO BE FREE OF CONTAMINATES PRIOR TO FINISH OR SHIPPING.
- 4. BAG OR TAG PART(S) WITH PART NUMBER, APPLICABLE DASH NUMBER, AND REVISION LEVEL.
- 5. MATERIAL:
- 6. FINISH:





For reference



THIRD ANGLE PROJECTION

ODC 48-xx QD